

## **Tunnel Lining Inspection**

### **Damage of cracks**

- Survey with high accuracy crack width, length, number, efflorescence, & water leakage
- Inspect tunnel attachment rust , damage, etc. with color images
- Compare to previous survey with high-precision analysis, and check progress of damages



## Measuring devise installation position



#### ■ 2013 Road surface performance test results

Test items	Scope of accreditation	Time of implementation	Result
Distance measurement accuracy	Distance measurement:±0.5% or less	Night	Pass
Crack measurement accuracy	Indetification accuracy:width more than 1mm	Night	Pass
Rut measurement accuracy	Rut depth:within±3mm	Night	Pass
Flatness measurement performance	Flatness:within±30%	Night	Pass

## **West Nippon Expressway Engineering Shikoku Company Limited**


〒760-0072 3-1-1 Hanazono-cho, Takamatsu-city tel.087-834-2386 fax.087-834-0150

For more information, NEXCO Shikoku

click!

# Inspection Without a Lane Closure

# **High Speed Pavement** and Tunnel Analyzer








Road surface inspection



## **Road surface inspection and tunnel lining** survey with one vehicle (6t car)


- Color photography with 100km/h speed, high-precision measurement
- Line illumination that does not inhibit general running vehicles

## **Road surface survey**



Cracks plan view by line scan camera: 0.8 ×0.5mm/pixel (speed 100km/h)

#### 2.Ruts




3D shape measurement by light cutting method

- A-A section
  - High-precision cross-section profile measurements
  - ·Height resolution: 0.5mm ·Measurement interval: 1.68 (width) × 5.6mm (length)
  - ·Shooting width: 4.4m

#### 3.Flatness

- High Resolution and accurate profiling vertical shape of a small step portion
- 3m profile, 8m profile, and IRI measurement are available
- Survey difference of level



## 4. Visual Analysis


**(1)View of amount depression (dip) by analysis of height information (Cracks inside** □**line)** 




Visible image



Crack location diagram






+ image analysis (Subsidence more than 5mm red)

Crack + image analysis (Subsidence more than 5mm)




#### 2)Three-stage display of rut amount



Rut analysis image (rut amount more than 5mm: red)

## **3 Blistering investigation**







direction (cm)

## **4** Aggregate scattering study of high-performance pavement (MPD)

- Strong correlation between MPD measured by CT meter and MPD measured by Eagle.\*\*)
- Plan aggregate scattering survey is available





A Study on quantification on aggregate scattering of drainage pavement, 63rd Annual Scientific Conference Japan Society of Civil Engineers, Sept.2008:Public Works Research Institute, Kano Takashi other

#### **5** Joint Survey








Image of joint

Situation of concrete protection Situation of joint rust and filling